

 **419-480-9118**
 **cs@toledo-tools.com**
 **www.toledo-tools.com**

TOLEDO TOOLS

PRODUCT CATALOG

Toledo Tools

Toledo, Ohio 43614
United States

419-480-9118 
cs@toledo-tools.com 

TOLEDO PIPE 86685 RED LOWER LEAD FITS RIDGID® 87740 300 MOTOR

SKU: TP-86685

PRICE: \$6.99



PRODUCT DESCRIPTION

Toledo Pipe Tools® is proud to give you alternative high quality replacement parts.

Red Lower Lead to brush holder fits the RIDGID® 300 / 300 Compact / 535 Motor

- Red lower lead to brush holder
- Replaces red lower lead in RIDGID® 300 87740 115v Motor
- Replaces red lower lead in RIDGID® 300 87780 230v Motor
- Replaces red lower lead in RIDGID® 300 61202 115v Motor
- Replaces red lower lead in RIDGID® 300 61207 230v Motor
- Replaces red lower lead in RIDGID® 300A 96810 115v Motor
- Replaces red lower lead in RIDGID® 300A 96975 230v Motor
- Replaces red lower lead in RIDGID® 300A 61192 115v Motor
- Replaces red lower lead in RIDGID® 300A 61197 230v Motor
- Replaces red lower lead in RIDGID® 300 Compact 72127 230v Motor
- Replaces red lower lead in RIDGID® 300 Compact 54797 115v Motor
- Replaces red lower lead in RIDGID® 300 Compact 54802 230v Motor
- Replaces red lower lead in RIDGID® 535 115v Motor (made Prior to 1994)
- Replaces RIDGID® Part: 86685

ADDITIONAL

INFORMATION

More Information

Manufacturer

Toledo Pipe Tools

Description

Toledo Pipe Tools® is proud to give you alternative high quality replacement parts.

Red Lower Lead to brush holder fits the RIDGID® 300 / 300 Compact / 535 Motor

- Red lower lead to brush holder
- Replaces red lower lead in RIDGID® 300 87740 115v Motor
- Replaces red lower lead in RIDGID® 300 87780 230v Motor
- Replaces red lower lead in RIDGID® 300 61202 115v Motor
- Replaces red lower lead in RIDGID® 300 61207 230v Motor
- Replaces red lower lead in RIDGID® 300A 96810 115v Motor
- Replaces red lower lead in RIDGID® 300A 96975 230v Motor
- Replaces red lower lead in RIDGID® 300A 61192 115v Motor
- Replaces red lower lead in RIDGID® 300A 61197 230v Motor
- Replaces red lower lead in RIDGID® 300 Compact 72127 230v Motor
- Replaces red lower lead in RIDGID® 300 Compact 54797 115v Motor
- Replaces red lower lead in RIDGID® 300 Compact 54802 230v Motor
- Replaces red lower lead in RIDGID® 535 115v Motor (made Prior to 1994)
- Replaces RIDGID® Part: 86685



419-480-9118



cs@toledo-tools.com



www.toledo-tools.com

TOLEDO TOOLS